

NOAO

ENGINEERING CHANGE ORDER

BOARD NAME <u>TORRENT Video Flex</u>	ECO# TRNT-004	DATE <u>Oct 8, 2009</u>
BRD SERL# _____ REV _____	ART# _____	
PN# _____ REV _____	REV _____	
ASBLY# <u>TRNT-EL-04-0005</u> REV <u>OD</u>	PCB# <u>TRNT-EL-04-1005</u> REV <u>OD</u>	
BOM# _____ REV _____	SCH# <u>TRNT-EL-04-2005</u> REV <u>OD</u>	
COGNIZANT ENGNR _____	APPROVD _____	

REASON FOR MODIFICATION:

Original release fab drawing caused the flex to be built in the wrong orientation.

DRAWINGS AFFECTED:	NEW REV
TRNT-EL-04-0005	A
TRNT-EL-04-1005	A
TRNT-EL-04-2005	A
TRNT-EL-04-3005	A
TRNT-EL-04-4005	A

DESCRIPTION OF MODIFICATION:

Correct the views on the fabrication drawing to build in the correct orientation.