

# NOAO

## ENGINEERING CHANGE ORDER

BOARD NAME <u>TORRENT Preamp CCD Transition</u>	ECO# <b>TRNT-006</b>	DATE <u>12/17/09</u>
BRD SERL# <u>001</u>	ART# _____	
PN# _____ REV _____		REV _____
ASBLY# <u>TRNT-EL-04-0007</u> REV <u>OD</u>	PCB# <u>TRNT-EL-04-1007</u>	REV <u>OD</u>
BOM# _____ REV _____	SCH# <u>TRNT-EL-04-2007</u>	REV <u>OD</u>
COGNIZANT ENGR _____	APPROVD _____	

REASON FOR MODIFICATION:

Connector positions are mirrored must be moved for correct orientation in the transition module.

DRAWINGS AFFECTED:	NEW REV
TRNT-EL-04-0007	A
TRNT-EL-04-1007	A
TRNT-EL-04-2007	A
TRNT-EL-04-3007	A
TRNT-EL-04-4007	A

DESCRIPTION OF MODIFICATION:

Reposition connectors and related circuitry for correct mounting in the transition module.